



AIK-01-0317

August 23, 2001

Project Number HK 7846

via US Mail

Byas Glover (Code 18410)
Department of the Navy
SOUTHDIV NAVFACENGCOM
P.O. Box 190010
North Charleston, South Carolina 29419-9010



Reference:

CLEAN Contract No. N62467-94-D-0888

Contract Task Order No. 059

Subject:

Professional Certification for the Groundwater Monitoring Well Report, Building 189,

Naval Air Station Key West, Florida

Dear Mr. Glover:

TtNUS is pleased to provide you with the enclosed Professional Certification for the Groundwater Monitoring Well Report for Building 189 Pipeline Site, Naval Air Station Key West, Florida. This certification was requested by Florida's Department of Environmental Protection (FDEP) in an email dated 27 July 2001. Because the report's recommendation for no further action was accepted by FDEP for the subject site, TtNUS plans to abandon the remaining 3 wells and then close out contract task order (CTO) 059.

Please call me at (803) 649-7963, extension 345, if you have any questions regarding the enclosed certification or CTO 059.

Sincerely,

C. M. Bryan Project Manager

CMB:spc

Enclosure

c: Ms. Debbie Wroblewski (Cover Letter Only)

Mr. Joe Fugitt, FDEP

File: 7846-7.4.1⋅

Mr. R. Courtright, NAS Key West

Mr. M. Perry/File

PROFESSIONAL CERTIFICATION

Groundwater Monitoring Report Building 189 Pipeline Site, Naval Air Station (NAS), Key West, Florida

This Groundwater Monitoring Report was prepared under the direct supervision of the undersigned geologist using geologic and hydrogeologic principles standard to the profession at the time the report was prepared. If conditions are determined to exist that differ from those described, the undersigned geologist should be notified to evaluate the effects of additional information on the assessment described in this report. This report was developed specifically for the referenced site and should not be construed to apply to any other site.

Gary Braganza, P.G.

Florida License No. PG-0001822

Date

PROFESSIONAL CERTIFICATION

Groundwater Monitoring Report Building 189 Pipeline Site, Naval Air Station (NAS), Key West, Florida

This Groundwater Monitoring Report was prepared under the direct supervision of the undersigned geologist using geologic and hydrogeologic principles standard to the profession at the time the report was prepared. If conditions are determined to exist that differ from those described, the undersigned geologist should be notified to evaluate the effects of additional information on the assessment described in this report. This report was developed specifically for the referenced site and should not be construed to apply to any other site.

Gary Bragar za, P.G.

Florida Licerse No. PG-0001822

Date

PROFESSIONAL CERTIFICATION

Groundwater Monitoring Report Building 189 Pipeline Site, Naval Air Station (NAS), Key West, Florida

This Groundwater Monitoring Report was prepared under the direct supervision of the undersigned geologist using geologic and hydrogeologic principles standard to the profession at the time the report was prepared. If conditions are determined to exist that differ from those described, the undersigned geologist should be notified to evaluate the effects of additional information on the assessment described in this report. This report was developed specifically for the referenced site and should not be construed to apply to any other site.

Gary Braganza, P.G.

Florida License No. PG-0001822

Date